

Service and replacement of discontinued RaySafe Xi instrumentation

After nearly 20 years on the market, all RaySafe Xi meters and associated detectors were discontinued on December 31, 2018. RaySafe Xi models are replaced by the corresponding RaySafe X2 models.

RaySafe guarantees that your Xi can be repaired and calibrated until December 31, 2023. Post this date, we cannot guarantee* calibration or service of any RaySafe Xi devices since many components are no longer available. If you have any questions regarding this notice, please contact your local RaySafe sales representative (<https://www.raysafe.com/contact>).



RaySafe Xi



RaySafe X2

*Calibration and service to be carried out on a “best effort” basis contingent with the availability of parts.

FLUKE
Biomedical

LANDAUER

RaySafe

Fluke Health Solutions

6920 Seaway Blvd, Everett, WA 98203 USA | (800) 850-4608